

SHOW REPORT FOR TEXAS VEHICLE REGISTRATION

TEXAS VEHICLE INSPECTION REPORT

SAFETY & EMISSION INSPECTION

44337

FOR INFORMATION ABOUT VEHICLE INSPECTION, VISIT www.dps.texas.gov/rsd/vi/. FOR INFORMATION ABOUT ONLINE VEHICLE REGISTRATION, VISIT www.twostepsonesticker.com.

Vehicle Identification

Test Date/Time: **02/18/2020, 14:41**
Test and Type: INITIAL - OBD Test
Insp. Type: **NLTSI**
Version/Test Number: 1804/001787
License Number: **VB085454**
Vehicle ID Number: **5FNRL38908B085454**
Vehicle Make: OTHR
Vehicle Model: ODYSSEY
Vehicle Year/Type: **2008 / TRUCK**
Engine Size/Cyl/Ign: 3500 / 6 / D
Authorization Number: **5EK6U54R139ZW**
Transmission/GVW: AUTOMATIC / 6019
Odometer/Fuel Type: 154768 / GASOLINE

Station Identification

Station Name: TAYLOR AUTO CREDIT
Station #/Analyzer: **6P41046 / WW540295**
Station Address: 200 PORTER STREET
Station City: TAYLOR
Station Zip Code: 76574-0000
Inspector First Name: PHILLIP
Inspector Last Name: MERAZ
Safety Inspection Fee: \$ 7.00
Safety Repair Costs: \$ 0.00
Emission Test Fee: \$ 11.50
Emission Repair Costs: \$ 0.00
Total Inspection Cost: \$ 18.50

Emissions Test Results

Status of Bulb Check	Monitors	Status	Monitors	Status	Monitors	Status	
MIL Cmd Status	Off	Misfire	Ready	Heated Cat	N/A	O2 Sens	Ready
MIL:		Fuel Sys	Ready	Evap	Ready	O2 Sens Htr	Ready
Engine On:	Pass	Comp Cmpnt	Ready	2nd Sys	N/A	EGR/VVT	Ready
Engine Off:	Pass	Catalyst	Ready	Air Cond	N/A	DLC	Pass


Fault Codes: No Codes Present

Gas Cap Missing: No Gas Cap Testable: Yes Gas Cap Integrity: PASS Safety Items: PASS

OVERALL RESULT: PASS

CONGRATULATIONS, your vehicle has passed the emissions (I/M) test portion of your annual safety inspection! By maintaining your vehicle in good working condition, you are doing your share for clean air. You are also saving money on gas and extending the life of your vehicle because your emissions control equipment is working as it should.

I certify that I have properly performed the emissions test according to state regulations and procedures manuals, and as the undersigned duly appointed inspection, hereby certify that I have physically examined the manufacturer's vehicle identification number of the motor vehicle described above.


Certified Inspector's Signature

VIN: 5FNRL38908B085454



Plate Type: 2, Plate Number: VB085454, TxDot:

